

Stock Number: 669925

Model: DB88 Serial Number: 1A0DB88XPCG750108

INSPECCIÓN EVALUACIÓN — ADVANCED — BRANDT PLANTERS

2012 John Deere DB88
 Inventario: 669925
 Serie: 1A0DB88XPCG750108
 Garantía desconocida

LOCALIDAD ALMACENAMIENTO
Valley Plains Equipment / 081249
 CROOKSTON, MN, 56716
 Contacto:

FOTOS (0 Total)

RESUMEN

Estado general:
Comentarios
generales:
Horas:

	E X C E L E N T E	B I E N	M E D I A N O	R A Z O N A B L E	M A L	N / A	Observaciones	Costo estimado		
								Repuestos	Mano de obra	Total
BRANDT PLANTERS								0	0	0
Availability Date								0	0	0
Monitors								0	0	0
Hydraulic Requirements								0	0	0
ROWS								0	0	0
FRAME								0	0	0
PLANTING UNITS								0	0	0
HOPPERS								0	0	0
FERTILIZER								0	0	0
CLOSING WHEELS-ROW CLEANERS								0	0	0
PHOTOS- minimum required pictures for evaluation								0	0	0
BMLSS- BROKEN-MISSING-LEAKING-SAFETY-SERVICE-								0	0	0
Pricing								0	0	0

BRANDT PLANTERS

							Costo estimado			
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra	Total
							This planter has gone over roughly 45,000 acres in its lifetime but has always been well maintained. Gudajtes family farms are the premier sugar growers in the area. If it needed fixing, they did it.			
What will the acres be when this planter comes in?							45,000			

AVAILABILITY DATE

							Costo estimado			
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra	Total
What is your anticipated availability date for this item? What is the MM/DD/YY this will be ready to deliver to the next buyer?							✓ What is your anticipated availability date for this item? When will it be on the lot ready to deliver to the next buyer? 9/1/23			
Does this planter have a John Deere Retrofit kit?							✓ Yes -Retrofit Kit- Please add Serial number in notes and Acres planted since installed Precision V set meters with speed tubes and hyd down force. Pneumatic adjust closing wheels. 2x2 Fertilizer will be coming off the machine. Will have regular gauge wheels when the 2X2 comes off.			

MONITORS

							Costo estimado			
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra	Total
What monitor was used to run this planter? Does the monitor come with the trade <input checked="" type="checkbox"/> Si <input type="checkbox"/> No							Will come with a precision 20/20 gen 3.			

HYDRAULIC REQUIREMENTS

							Costo estimado			
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra	Total
How many SCV's needed							✓ 6			
How many power beyond?							✓ 1			

ROWS

							Costo estimado			
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra	Total
NUMBER OF ROWS							✓ 48 ROW			
SPACING							✓ 22 INCH			

FRAME

							Costo estimado			
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra	Total
							✓ DB BAR			
DOES IT HAVE MARKERS? <input type="radio"/> Si <input checked="" type="radio"/> No										

PLANTING UNITS

							Costo estimado			
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra	Total
UNIT TYPE							✓ Precision or other aftermarket system			
DOWN PRESSURE							✓ INDEPENDENT HYDRAULIC			
What is the disk measurement?							close to 14.5" need replacing.			

HOPPERS

							Costo estimado			
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra	Total
							✓ CENTRAL COMMODITY SYSTEM			

FERTILIZER

							Costo estimado			
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra	Total
FERTILIZER SYSTEM							✓ LIQUID IN-FURROW ground drive fert in furrow. The 2x2 in the pics will be removed.			

CLOSING WHEELS-ROW CLEANERS

							Costo estimado			
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra	Total
CLOSING WHEEL-ROW CLEANERS							✓ PNEUMATIC CONTROLLED RUBBER CLOSING WHEELS one rubber, one spiked			
ROW TILLAGE ADJUST										

PHOTOS- MINIMUM REQUIRED PICTURES FOR EVALUATION

							Costo estimado			
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra	Total
Did you take pictures of the following?							✓ Serial number plate			

BMLSS- BROKEN-MISSING-LEAKING-SAFETY-SERVICE-

	N U E V O	B I E N	U T I L I Z A B L E	R E P A R A R	R E M P L A Z A R	N D	Observaciones	Costo estimado		
								Repuestos	Mano de obra	Total
Each section must be completed or it will be returned-							✓ Each section must be completed or it will be returned-			
My expected broken items cost and description							✓ No Broken Items			
My missing items replacement cost and description							✓ No missing items			
My expected leaking items cost and description							✓ No leaking items			
My expected safety items cost and description							✓ No safety items to fix			
My expected Service costs and description (Example:oil-fluids-filters-wash)							✓ Cost and description of oil-fluids-filters and wash and to put on front line-enter in notes \$4500 for new seed openers, \$1500 for misc repairs			

PRICING

	N U E V O	B I E N	U T I L I Z A B L E	R E P A R A R	R E M P L A Z A R	N D	Observaciones	Costo estimado		
								Repuestos	Mano de obra	Total
Total BMLSS cost (must be broken down in section above)							✓ Total BMLSS cost (must be broken down in section above) \$6000			
My Expected Sale Price							\$315,000			