Stock Number: 231922 Model: Z6**§**Frial Number: 1M0Z645VPCM120816

# INSPECCIÓN EVALUACIÓN — ADVANCED — WI GENERAL SALES EVALUATION INSPECTION

2012 John Deere Z645 Inventario: 231922 Serie: 1M0Z645VPCM120816 Garantía desconocida LOCALIDAD ALMACENAMIENTO Wright Implement 1, LLC / 038458 SELLERSBURG, IN, 47172 Contacto:

### FOTOS (0 Total)

#### **RESUMEN**

Estado general: Comentarios generales: Horas:

								Cost	o estimado		
	EXCELENTE	B I E N	MEDIANO	RAZONABLE	M A L	N / A	Observaciones	Repuestos	Mano de obra	Total	
General Overview			Х					0	0	0	
RECEIVING On Lot sales verification (Complete this section once received on lot or on farm at time of trade pickup)								0	0	0	

Stock Number: 231922 Model: Z695rial Number: 1M0Z645VPCM120816

#### **GENERAL OVERVIEW**

						Costo estimado				
	NUEVO	B I E N	UTILIZABLE	REPARAR	REEMPLAZAR	N D	Observaciones	Repuestos	Mano de obra	Tota
List the MAIN FEATURES and options:	Ĭ			,			MOWER LOOKS GOOD OPERATES AS IT SHOULD. GOOD SEAT.			
Number of HOURS, BALES, ACRES, if available; or estimate of use (low, med, high):							641 HOURS			
Describe the GENERAL CONDITION and select an overall condition rating:			x				ENGINE OIL LEAK FROM LOWER SEAL POSSIBLE PAN GASKET LEAKING OIL AND DIRT ALL OVER LOWER ENGINE			
What KEY FUNCTIONS or components are not working correctly, missing, damaged OR nave ANY ISSUES? Describe:							BAD ENGINE OIL LEAK			
Describe condition and identify any ISSUES WITH FRAME, cab, nood, lights, tires, or any other components not listed above:			x							
List COMPONENTS that come with this equipment that are separate or NOT ATTACHED displays, monitors, weights, attachments like bale spear, buckets, mower deck, etc AND ndicate any issues with condition of each:		•								
f the trade is made, what cleanup or repairs or RECONDITIONING WOULD YOU RECOMMEND we complete in order for you (or someone else) o sell this to one of your customers?							REPAIR LOWER ENGINE OIL LEAK \$500-750 ESTIMATE BEFORE TEAR DOWN			

## RECEIVING -- ON LOT SALES VERIFICATION (COMPLETE THIS SECTION ONCE RECEIVED ON LOT OR ON FARM AT TIME OF TRADE PICKUP)

								Costo estimado				
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	N D	Observaciones	Repuestos	Mano de obra	Total		
Does the condition of this trade match expected condition based on the inspection at time of evaluation?							REPAIRS TO OIL LEAK NEW DRIVE BELT NEW BLADES					
Date this was verified:							7/9/2025					
Verified by:							WALTER	<del> </del>				