

INSPECCIÓN EVALUACIÓN — ADVANCED — BRANDT ROW CROP-UTILITY TRACTORS

2024 John Deere 5095M

Inventario: 667859

Serie: 1PY5095MTRB000754

Garantía desconocida

LOCALIDAD ALMACENAMIENTO

Kibble Equipment / 089338

BELLE PLAINE, MN, 56011

Contacto:

FOTOS (0 Total)

RESUMEN

Estado general:
Comentarios
generales:
Horas:

	E X C E L E N T E	B I E N	M E D I A N O	R A Z O N A B L E	M A L	N / A	Observaciones	Costo estimado		
								Repuestos	Mano de obra	Total
Availability Date/Hours								0	0	0
All evaluations								0	0	0
BRANDT ROW CROP-UTILITY TRACTORS								0	0	0
Transmission	X							0	0	0
Front Axle	X							0	0	0
FRONT TIRES								0	0	0
Rear Tires	X							0	0	0
Estación del Operador	X							0	0	0
Power Take off								0	0	0
Hydraulics								0	0	0
WEIGHTS								0	0	0
Rock Box								0	0	0
LOADER								0	0	0
General Notes								0	0	0
PHOTOS- minimum required pictures for evaluation								0	0	0
BMLSS- BROKEN-MISSING-LEAKING-SAFETY-SERVICE-Pricing								0	0	0
BRANDT ROW CROP-UTILITY TRACTORS								0	0	0

Stock Number: 667859

Model: 5095M Serial Number: 1PY5095MTRB000754

AVAILABILITY DATE/HOURS

							Costo estimado			
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra	Total
What is your anticipated availability date for this item? What is the MM/DD/YY this will be ready to deliver to the next buyer?							✓ What is your anticipated availability date for this item? When will it be on the lot ready to deliver to the next buyer? MUST REMAIN IN DPFR UNTIL 11/23/24 AND THEN BE SOLD AS USED			
PLEASE BE SPECIFIC ABOUT CURRENT ENGINE HOURS AND WHAT THEY WILL BE WHEN AVAILABLE FOR RESALE							✓ PLEASE BE SPECIFIC ABOUT CURRENT ENGINE HOURS AND WHAT THEY WILL BE WHEN AVAILABLE FOR RESALE			
LOADERS OR ANY SERIAL NUMBERED ATTACHMENT MUST HAVE THE SERIAL NUMBER LOADED AS PART OF THE INSPECTION										

ALL EVALUATIONS

							Costo estimado			
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra	Total
Please fill out evaluation 100% complete, including name and date. Check appropriate boxes and notes made for each section as needed. List all options pertinent to the unit even if there isn't a box for the option. Make notes for options shown in pictures if the option is to stay with the machine or if it is to be removed. Be specific. Having all the information available will expedite the evaluation being returned to you. Thank you for your assistance.										

BRANDT ROW CROP-UTILITY TRACTORS

							Costo estimado			
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra	Total
Has this machine had a power chip? ☐ Si ☒ No										
Has the factory equipped DEF system been removed? ☐ Si ☒ No										

TRANSMISSION

							Costo estimado			
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra	Total
Type of transmission Hours since transmission oil/filter changed? / Does transmission shift properly in all gears?	X						✓ Powerquad 16SPD			
Hour meter reading when transmission oil and filter was changed last?										

Stock Number: 667859

Model: 5095M Serial Number: 1PY5095MTRB000754

FRONT AXLE

							Costo estimado			
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra	Total
Axle Type Take pictures of both front and rear tires to show estimated tread remaining. Take pictures of face to assess stubble damage and sides for any cuts or tears.	X						✓ MFWD			

FRONT TIRES

							Costo estimado			
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra	Total
TIRE SIZE Front duals? ☐ Si ☐ No							✓ 380/85R24			
Front Tread Remaining							✓ New tires-No Hours			

REAR TIRES

							Costo estimado			
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra	Total
Rear Tire Size	X						✓ OTHER (please put in notes) 460/85R34			
							✓ SINGLES			
Rear Tread Remaining							✓ New tires-No hours			

ESTACIÓN DEL OPERADOR

							Costo estimado			
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra	Total
Operator station Type Any cuts or tears in the seat? Has the cab been smoked in? Is the headliner in place? Take pictures of the hour meter and controls inside the cab.	X						✓ Factory Cab			

POWER TAKE OFF

							Costo estimado			
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra	Total
Type Take a picture of the power take off shaft etc							✓ 540E/540/1000 PTO			

Stock Number: 667859

Model: 5095M Serial Number: 1PY5095MTRB000754

HYDRAULICS

							Costo estimado			
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra	Total
Hydraulic Type Take a picture so we can see all of the SCV and any power beyond hookups.							✓ 3SCV LDR MULTI POINT COUPLER			

WEIGHTS

							Costo estimado			
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra	Total
Front Weights in #LBS Take picture of front weights										
Rear Weights in #LBS Take picture of rear weights										

ROCK BOX

							Costo estimado			
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra	Total
ROCK BOX							✓ No Rock Box			

LOADER

							Costo estimado			
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra	Total
GENERAL CONDITON OF LOADER. ANY WELDS GUSSETS OR MAJOR REPAIRS?										
LOADER MAKE/MODEL										
Serial number of loader and picture of serial number must be added for Eval										

GENERAL NOTES

							Costo estimado			
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra	Total
Overall notes on unit										

PHOTOS- MINIMUM REQUIRED PICTURES FOR EVALUATION

							Costo estimado			
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra	Total
Do you have pictures of? Minimum required pictures							✓ Minimum required pictures for evaluation WILL NEED PHOTOS TAKEN IN BELLE PLAINE			

BMLSS- BROKEN-MISSING-LEAKING-SAFETY-SERVICE-

							Costo estimado			
	N U E V O	B I E N	U T I L I Z A B L E	R E P A R A R	R E E M P L A Z A R	N D	Observaciones	Repuestos	Mano de obra	Total
EACH SECTION MUST BE COMPLETED OR IT WILL BE RETURNED							✓ Each section must be completed or it will be returned			
My expected broken items cost and description							✓ No broken items			
My missing items replacement cost and description							✓ No missing items			
My expected leaking items cost and description							✓ No Leaking items			
My expected safety items cost and description							✓ No safety items to fix			
My expected Service costs and description (Example:oil-fluids-filters-wash)							✓ Cost and description of oil-fluids-filters and wash and to put on front line-enter in notes HAS BEEN PDI'D			

PRICING

								Costo estimado		
	N U E V O	B I E N	U T I L I Z A B L E	R E P A R A R	R E E M P L A Z A R	N D	Observaciones	Repuestos	Mano de obra	Total
Total BMLSS cost (must be broken down in section above)							\$622			
My Expected Sale Price							\$106000			

BRANDT ROW CROP-UTILITY TRACTORS

							Costo estimado		
NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra	Total