

# SALES COMBINE INSPECTION WORKSHEET

Manufacturer: JD Model 9670

Year 10 Serial Number 1H09670SCA236261

Customer Name Loren Newjahr

### Machine History:

Purchased New  Purchased Used Purchased from Bowlington Equipment

Engine Hours 818 Separator Hours 573 Years owned 3

### Heads Used On Combine:

Cornhead: Model 608C Rows \_\_\_\_\_ Row Width \_\_\_\_\_

Flex Platform: Model 625 Width \_\_\_\_\_

Rigid Platform: Model \_\_\_\_\_ Width \_\_\_\_\_

Other: Model \_\_\_\_\_ Width \_\_\_\_\_

### Acres Farmed:

Total \_\_\_\_\_ Corn \_\_\_\_\_ Soybeans \_\_\_\_\_ Wheat \_\_\_\_\_ Other \_\_\_\_\_

Customer is Buying S660

### Description of Equipment:

---

---

---

---

---

### Type of Combine:

Small Grain  Corn/Bean  Sidehill  STS  Rotor  Walker  
 Custom Cutter Package  Other

### Front Tires:

Single - Size \_\_\_\_\_  Duals - Size 18.4R24

Stubble Damage Tread 80 %

**Rear Axle:**

2WD  PRWD

Size 16.4R26  Stubble Damage Tread 80 %

**Monitor/GPS:**

Yield Monitor  Mapping  AutoTrac  Harvest Smart Header Control

**Operator Station:**

Deluxe Cab  Premium Cab  Premier Cab  Power Adjust Mirrors

**Transmission:**

Hydro  2-Speed Pro Drive W/HarvestSmart

**Threshing: Concave**

Small Wire  Large Wire  Round Bar  Extended Wear

**Grain Handling:**

Standard Unload Auger  Long Unload Auger  Extended Wear

Grain Tank Extension  Brand: Mauer Tip Up

**Feederhouse:**

LL W/Reverser & Reg Duty Variable  LL W/Reverser & HD Variable  
 LL W/Reverser & HD Variable  LL W/Reverser & Hi-Torque Variable  
 CM W/Reverser & HD Variable  CM W/Reverser & Hi-Torque Variable  
 CM W/Reverser & Command Touch Multi-Speed Drive  
 2.75" Lift Cylinders  3.15" Lift Cylinders

**Cleaning Shoe:**

General Purpose Adjustable Chaffer & Bottom Sieve  
 Deep Tooth Adjustable Chaffer & Bottom Sieve  
 SLS – W/General Purpose Adjustable Chaffer & Bottom Sieve  
 SLS – W/Deep Tooth Adjustable Chaffer & Bottom Sieve

**Residue Disposal:**

Fine Cut, 2 Speed Chopper W/Integrated Chaff Spreader  
 Fine Cut, 2 Speed Chopper W/Integrated Chaff Spreader & PowerCast Tailboard  
 Twin Disk Straw Spreader W/Integrated Chaff Spreader

## COMBINE INSPECTION WORKSHEET

### Paint Quality:

Like New  Faded  Average  Repainted

### Feederhouse:

Frame; Cracked or Twisted

OK  Needs Repair

Comments: \_\_\_\_\_

Floor: Holes / Worn Seals

OK  Needs Repair Comments: \_\_\_\_\_

Feederhouse Chain & Sprockets:

OK  Needs Repair  25%  50%  75% Comments \_\_\_\_\_

Rock Trap Door: Wear

OK  Needs Repair Comments: \_\_\_\_\_

Feed Accelerator: Wings  Serrated  Smooth

OK  Needs Repair Comments: *need tuned*

Feederhouse Drive:

Reg Duty  HD Hi-Torque  5-Speed

OK  Needs Repair  N/A Comments: \_\_\_\_\_

### Drives:

Primary Counter Shaft & Electric Clutch

OK  Needs Repair Comments: \_\_\_\_\_

Reel Pump Drive Bearings:

OK  Needs Repair Comments: \_\_\_\_\_

Main Gear Case Drive Shaft & Pillow Blocks:

OK  Needs Repair Comments: \_\_\_\_\_

Cleaning Shoe Drive Bearings

OK  Needs Repair Comments: \_\_\_\_\_

**Threshing & Separating:**

Threshing Elements:

OK  Needs Repair  N/A Comments: \_\_\_\_\_

Separator Tines:

OK  Needs Repair  N/A Comments: \_\_\_\_\_

Rotor Cover:

OK  Needs Repair  N/A Comments: \_\_\_\_\_

Rasp Bars:

OK  Needs Repair  N/A Comments: \_\_\_\_\_

Straw Walkers / Crank / Bearings:

OK  Needs Repair  N/A Comments: \_\_\_\_\_

**Cleaning Fan:**

Fan Blades:

OK  Needs Repair Comments: \_\_\_\_\_

Fan Bearings:

OK  Needs Repair Comments: \_\_\_\_\_

**Grain Tank:**

Floor:

OK  Needs Repair Comments: \_\_\_\_\_

Charge Housing Area:

OK  Needs Repair Comments: \_\_\_\_\_

Cross Augers:

OK  Needs Repair Comments: \_\_\_\_\_

Fountain Auger:

OK  Needs Repair Comments: needs auger \$1000.00

**Engine Compartment:**

Radiator / Fan / Air to Air After Cooler:

OK  Needs Repair  N/A Comments: \_\_\_\_\_

---

**Chopper:**

Rotor / Bearings:

OK  Needs Repair  N/A Comments: \_\_\_\_\_

---

Chopper Knives:

OK  Needs Repair  N/A Comments: \_\_\_\_\_

---

Discharge Beater Wings:

OK  Needs Repair  N/A Comments: \_\_\_\_\_

---

**Grain Handling:**

Clean Grain Elevator / Chain / Paddles / Cross Auger:

OK  Needs Repair Comments: \_\_\_\_\_

---

Tailings Return Elevator/ Chain / Paddles / Cross Auger

OK  Needs Repair  Comments: \_\_\_\_\_

---

Moisture Sensor

OK  Needs Repair  N/A Comments: \_\_\_\_\_

---

Overall Machine Rating (1 to 10): 9

1 = Nonfunctional, scrap only 5 = Average condition, repairs may be needed 10 = New

What components / attachments are on the combine and in the pictures that **WILL NOT** be included as part of the trade?

---

---

---

---

---

---

Examined By: Scott Herdewey

Date: 10-16-2012