

# TRACTORS - UTILITY MACHINE ENTRY FORM

Page 1

Manufacturer: FORD  
Model: 1510  
Year: 1984  
Serial Number: UH01833  
Storage Location/Notes: KFR  
Tag Number: 88068

Customer  
Traded From Ender  
Customer's Address:  
\_\_\_\_\_  
\_\_\_\_\_  
Advertised Price: 4900<sup>00</sup>  
Wholesale Price: \_\_\_\_\_  
Warranty End Date: N/A

Description of Equipment:

1984 FORD 1510, R3 Turf Tires, Starts and runs good

### KEY CODES:

Engine Hours: 185

Power Output: \_\_\_\_\_

Configuration:

- Standard  Low Profile  Narrow  
 High Clearance  Mudder

Operator's Station:

- No Cab  Cab  Cab w/o AC

Front Axle or Drive System:

- 2WD  MFWD  MFWD w/ Suspension  
 Tracks

Transmission:

- Powershift  Partial Powershift  
 Infinitely Variable  Hydro  
 Synchro  Synchro w/Hi-Lo  
 Collarshift  Creeper  Reverser

Speeds Forward: 12  
Speeds Reverse: 4

Loader:  Yes  No Describe: \_\_\_\_\_

Rear Tire Size: 9.5-24 R3 (Turf)

Radials:

- Radials  Bias

Front Tire Size: 7-14 R3 (Turf)

Tire Tread Remaining:

Rear: 60 %  
Front: 60 %

3 Point Hitch:

- None  Standard  Optional Lift Capacity

PTO:

- None  540 rpm  540/1000 rpm  
 540/540E/1000 rpm  1000 rpm

SCVs:

- None  1  2  3  4  5  6

Weights:

Front Quantity 80lbs.  
 Rear Quantity \_\_\_\_\_

Options:

- Quick Hitch  Radar  Optional Seat  
 Front hitch  Front PTO  Front Duals

Additional Options or Attachments:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

# UTILITY TRACTORS INSPECTION

**Paint Quality:**

- Like New  Faded
- Average  Repainted

**Standard Equipment that is Damaged or Missing:**

Hood has minor scratches  
Paint is faded

**A. Engine, Cooling and Fuel Systems:**

Block, cyl head, valve cover, oil pan & gaskets

- OK  Needs Repair  N/A

Comments: \_\_\_\_\_

Air intake, filter, tubes, hoses & clamps

- OK  Needs Repair  N/A

Comments: \_\_\_\_\_

Radiator, cap, water pump, hoses & tubes

- OK  Needs Repair  N/A

Comments: \_\_\_\_\_

Exhaust system pipes, muffler & turbo

- OK  Needs Repair  N/A

Comments: \_\_\_\_\_

Inj. pump, fuel lines, tank & fuel filter

- OK  Needs Repair  N/A

Comments: \_\_\_\_\_

Crankshaft, damper & pulleys

- OK  Needs Repair  N/A

Comments: \_\_\_\_\_

Engine running test for power, leaks, unusual noises or smoke

- OK  Needs Repair  N/A

Comments: \_\_\_\_\_

**B. Power Train:**

Clutch slippage & operation

- OK  Needs Repair  N/A

Comments: \_\_\_\_\_

PTO clutch & brake operation

- OK  Needs Repair  N/A

Comments: \_\_\_\_\_

Transmission & controls operations

- OK  Needs Repair  N/A

Comments: \_\_\_\_\_

Rear axles and final drives, seals & bearings

- OK  Needs Repair  N/A

Comments: \_\_\_\_\_

Differential lock operation

- OK  Needs Repair  N/A

Comments: \_\_\_\_\_

Front axle assembly, seals, drive shafts and u-joints

- OK  Needs Repair  N/A

Comments: \_\_\_\_\_

Leaks or noises

- OK  Needs Repair  N/A

Comments: \_\_\_\_\_

**C. Hydraulic System:**

Main Pump, pump drive, and operation

- OK  Needs Repair  N/A

Comments: \_\_\_\_\_

Rockshaft, hitch, operation & cycle time

- OK  Needs Repair  N/A

Comments: \_\_\_\_\_

Draft sensing system operation

- OK  Needs Repair  N/A

Comments: \_\_\_\_\_

SCV's, operation and cycle time

- OK  Needs Repair  N/A

Comments: \_\_\_\_\_

Any leaks? Lines, hoses & clamps condition

- OK  Needs Repair  N/A

Comments: \_\_\_\_\_

**D. Electrical Systems:**

Battery, cables and wiring harness

- OK  Needs Repair  N/A

Comments: \_\_\_\_\_

Starter switch, motor & neutral safety system

- OK  Needs Repair  N/A

Comments: \_\_\_\_\_

Lights, warning lights & turn signals

- OK  Needs Repair  N/A

Comments: 2 Fender Lights, 1 Rear Worklight

Tachometer, gauges & indicator lights

- OK  Needs Repair  N/A

Comments: \_\_\_\_\_

**E. Steering & Brakes:**

Steering valve, motor, cylinders & hoses

- OK  Needs Repair  N/A

Comments: \_\_\_\_\_

# UTILITY TRACTORS INSPECTION

Steering operation & free travel  
 OK  Needs Repair  N/A

Comments: \_\_\_\_\_

Tie rods, drag link & steering arm  
 OK  Needs Repair  N/A

Comments: \_\_\_\_\_

Brake valve & brake operation  
 OK  Needs Repair  N/A

Comments: \_\_\_\_\_

### F. Operators Station:

Seat condition & operation  
 OK  Needs Repair  N/A

Comments: \_\_\_\_\_

Cab, glass, upholstery & moldings condition  
 OK  Needs Repair  N/A

Comments: \_\_\_\_\_

Heater & A/C systems and operation  
 OK  Needs Repair  N/A

Comments: \_\_\_\_\_

Door, latch, and hinges condition & operation  
 OK  Needs Repair  N/A

Comments: \_\_\_\_\_

### G. Miscellaneous:

Draw bar, 3 pt. mounts, links & couplers  
 OK  Needs Repair  N/A

Comments: Top link missing

Chassis, frame, weights & hardware  
 OK  Needs Repair  N/A

Comments: \_\_\_\_\_

Sheet metal & paint condition & appearance  
 OK  Needs Repair  N/A

Comments: Paint is Faded

Wheel & tire condition & appearance  
 OK  Needs Repair  N/A

Comments: \_\_\_\_\_

### H. Safety Equipment:

Oil, fuel & coolant leaks  
 OK  Needs Repair  N/A

Comments: \_\_\_\_\_

All safety shields, covers & shrouds  
 OK  Needs Repair  N/A

Comments: \_\_\_\_\_

SMV, safety decals & warning devices  
 OK  Needs Repair  N/A

Comments: \_\_\_\_\_

Steps, handrails, fenders & guards  
 OK  Needs Repair  N/A

Comments: \_\_\_\_\_

Overall Machine Rating (1 to 10): 6

1 = Nonfunctional, scrap only.

5 = Average condition, repairs may be needed.

10 = New and unused.

Examined by: Shane Clifton

Date: 3-27-14