

Used Equipment Checklist

EQUIPMENT INFORMATION				
Stock #:	Make:	JD		
Model: 260	Location:	BB		
PHOTOGRAPHS REQUIRED				
☐ 1- Serial Number # KVO 26OA 26 O IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	100	-		
CONDITION INFORMATION				
Yes No ☐ Interior Clean ☐ Exterior Clean				
Comments:				
CONDITION LEVEL				of No. 1884
 ☐ Excellent - Looks new and is in excellent condition ☐ Good - Has a few minor cosmetic defects ☑ Fair - Has some cosmetic defects that require repairing and/or Poor - Has many cosmetic defects that require repairing and/or 				
☐ Good - Has a few minor cosmetic defects ☐ Fair - Has some cosmetic defects that require repairing and/or				
Good - Has a few minor cosmetic defects Fair - Has some cosmetic defects that require repairing and/or Poor - Has many cosmetic defects that require repairing and/or			9	
Good - Has a few minor cosmetic defects Fair - Has some cosmetic defects that require repairing and/or Poor - Has many cosmetic defects that require repairing and/or				
Good - Has a few minor cosmetic defects Fair - Has some cosmetic defects that require repairing and/or Poor - Has many cosmetic defects that require repairing and/o Condition Comments:	or replacing			
Good - Has a few minor cosmetic defects Fair - Has some cosmetic defects that require repairing and/or Poor - Has many cosmetic defects that require repairing and/o Condition Comments: DEFECTS Comments on any obvious or known defects: - Over head Cabwindow glass missing and/or - door colless were	or replacing			
Good - Has a few minor cosmetic defects Fair - Has some cosmetic defects that require repairing and/or Poor - Has many cosmetic defects that require repairing and/or Condition Comments: DEFECTS Comments on any obvious or known defects: - over head Cabwindow glass missing - door collers were - bucket is rough GENERAL COMMENTS	or replacing			
Good - Has a few minor cosmetic defects Fair - Has some cosmetic defects that require repairing and/or Poor - Has many cosmetic defects that require repairing and/o Condition Comments: DEFECTS Comments on any obvious or known defects: - Over head Cabwindow glass missing the college were bucket is rough	or replacing			