

SEMA EQUIPMENT. INC.

2001 4th Street NW
 Austin, MN 55912
 Phone: 507-437-6625

Spring Valley, MN 507-346-7375
 Plainview, MN 507-534-3116
 St. Charles, MN 507-932-4030
 Wanamingo, MN 507-824-2256
 Leroy, MN 507-324-5201
 Northfield, MN 507-645-4886
 Caledonia, MN 507-725-7000



JOHN DEERE

Invoice To Account No.:

Deliver To:

*** DOCUMENT COPY ***

SERVICE INVOICE

Internal Used Stock No. 40584	Internal Used Stock No. 40584	Invoice Number: 514649 Invoice Date: 5/16/2013 Branch: 6 Repair Order Number: 80778 Payment Type: Account Page: 1 of 2
Bus Phone:	Bus Phone:	
Prv Phone:	Prv Phone:	

Make/Model: OHN DEERE 930F FLEX PLAT
Meter Reading:
Serial Number: H00930F697816
Equipment Number: F697816

/2012 PLATFORM INSP Internal

COMPLAINT:
 PLATFORM INSPECTION \$99.00.LEVEL DIVIDER POINTS
 INSPECT REEL FOR WORN PARTS
 INSPECT THE SKID PLATE AND SEALS
 CHECK SICKLE WEAR PLATES HOLD DOWN AND GUARDS
 INSPECT ALL DRIVE AND BEARINGS

\$105.00

CORRECTION:
 LEVEL DIVIDER POINTS
 INSPECT REEL FOR WORN PARTS
 INSPECT THE SKID PLATE AND SEALS
 CHECK SICKLE WEAR PLATES HOLD DOWN AND GUARDS
 INSPECT ALL DRIVE AND BEARINGS

Service Accessories

Service Accessories

\$18.82

Labor: \$105.00 Parts: \$0.00 Sublet: \$0.00 Misc: \$18.82 Total: \$123.82

GEN-1 Internal

COMPLAINT:
 Replace Drive Belt.REMOVED SIDE SHEILD AND MOUNTING BOLT FOR WOBBLE BOX TO GET OLD BELT OFF AND
 INSTALL NEW BELT REINSTALL SHEILD AND TIGHTEN ALL BOLTS AND ADJUSTED BELST TIGHTNER.

\$501.66

CORRECTION:
 Replace Drive Belt.REMOVED SIDE SHEILD AND MOUNTING BOLT FOR WOBBLE BOX TO GET OLD BELT OFF AND
 INSTALL NEW BELT REINSTALL SHEILD AND TIGHTEN ALL BOLTS AND ADJUSTED BELST TIGHTNER.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>Unit Nett</u>	<u>Value</u>	<u>Taxed Ind</u>
BLUE	Grade 8 hdwe	2.00	0.29	\$0.58	N

SEMA EQUIPMENT. INC.

2001 4th Street NW
 Austin, MN 55912
 Phone: 507-437-6625

Spring Valley, MN 507-346-7375
 Plainview, MN 507-534-3116
 St. Charles, MN 507-932-4030
 Wanamingo, MN 507-824-2256
 Leroy, MN 507-324-5201
 Northfield, MN 507-645-4886
 Caledonia, MN 507-725-7000



JOHN DEERE

Invoice To Account No.:

Deliver To:

*** DOCUMENT COPY ***

SERVICE INVOICE

Internal Used Stock No. 40584	Internal Used Stock No. 40584	Invoice Number: 514649
		Invoice Date: 5/16/2013
		Branch: 6
		Repair Order Number: 80778
		Payment Type: Account
Bus Phone:	Bus Phone:	Page: 2 of 2
Prv Phone:	Prv Phone:	

Make/Model: OHN DEERE 930F FLEX PLAT
 Meter Reading:
 Serial Number: H00930F697816
 Equipment Number: F697816

GEN-1 Internal						
H138762	V-BELT	1.00	60.48	\$60.48	N	
Labor: \$501.66	Parts: \$61.06	Sublet: \$0.00	Misc: \$0.00	Total: \$562.72		

GEN-2 Internal
 COMPLAINT: \$273.34
 Wash. OFF ALL OIL AND DIRT FROM PLATFORM.

CORRECTION:

Labor: \$273.34	Parts: \$0.00	Sublet: \$0.00	Misc: \$0.00	Total: \$273.34
------------------------	----------------------	-----------------------	---------------------	------------------------

Customer PO No.:	
Tax Exempt No.:	
Advisor:	Ron Nelson

Labor:	\$880.00
Parts:	\$61.06
Sublet:	\$0.00
Misc:	\$18.82
Sales Tax:	\$0.00
Total:	<u>\$959.88</u>

TERMS AND CONDITIONS

TERMS: PAYMENT DUE IN FULL UPON COMPLETION OF REPAIRS!
 90 Days defective parts and labor warranty on all repair performed unless otherwise specified

Received by: Date: