

Stock Number: 256276

Model: 338A

Serial Number: 14854222



INSPECCIÓN EVALUACIÓN — ADVANCED — TILLAGE AND FIELD PREP JANUARY 2023

2022 Brandt 338A
Inventario: 256276
Serie: 14854222
Garantía desconocida

LOCALIDAD ALMACENAMIENTO
Pattison Agriculture Limited / 731854
Kelvington, SK, S0A 1W0
Contacto:

FOTOS (0 Total)

RESUMEN

Estado general:
Comentarios
generales:
Horas:

								Costo estimado		
	E X C E L E N T E	B I E N	M E D I A N O	R A Z O N A B L E	M A L	N / A	Observaciones	Repuestos	Mano de obra	Total
								0	0	0
MAIN FEATURES TO BE ADVERTISED - FILL IN FEATURES SECTION OF MFPRO								0	0	0
INSPECTION/CONDITIONS-TOOL								0	0	0

Stock Number: 256276

Model: 338A

Serial Number: 14854222

							Costo estimado		
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra Total
Customer:							BANDURA ACRES		
Year: Make: Model:							2022 Brandt 338A		
Serial Number:							14854222		
Approx. Acres:									
Link to Picture Process:									

MAIN FEATURES TO BE ADVERTISED - FILL IN FEATURES SECTION OF MFPRO

							Costo estimado		
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra Total
1- Width							37' 4" Working Width		
							38' Three Section High Speed Disk Hydraulic Front Jack		
2- Attachment: Year: Make: Model									
3- Serial Number:									
4- Weight Package/ Amount of Weights									
5- Front Tires: Brand and Size							Front Transport BKT 600/50R22.5 Tires		
Rear Tires: Brand and Size							Outside Wing 550/45-22.5 Tires		
6- Heavy Harrow Tine Bar									
7- Harrow Bar Tines									
8- Disc Type							✓ Smooth Smooth Rear 17 Degree Angled Disks On Rubber Torsion Arms Front Wavy 14 Degree Angled Disks On Rubber Torsion Arms 5" Disk Spacing		
9- Rear of Unit							Rear Corrugated Rubber Rollers w/ Hydraulic Adjustable Scraper Option Rear Finishing Suspension Option		

Stock Number: 256276

Model: 338A

Serial Number: 14854222

INSPECTION/CONDITIONS-TOOL

							Costo estimado			
	N U E V O	B I E N	U T I L I Z A B L E	R E P A R A R	R E M P L A Z A R	N D	Observaciones	Repuestos	Mano de obra	Total
							✓ Operators Manual No Not in Holder but I would think customer has			
1- Front Tires Condition and % Remaining							nice condition			
Measured vs New Tread Height							31/32 vs 36 86%			
Rear Tires Condition and % Remaining							wing tires nice condition			
Measured vs New Tread Height							30/32 vs unknown aprox. 90%			
2- Hitch & Frame							✓ Good			
3- Wing and Depth Cycl.							✓ Good			
4- Hinge/ Fold Pins/ Hyd. Hoses/ Valve Blocks/ Lights/ SMV							✓ Good			
5- Rear Unit							✓ Packers			
6- C Shank: Spacing										
7- Trip Force										
8- LB. Opener/ Shovel Style										
9- Disc							✓ Good			
Disc Size/ % Remaining							wavy 19 to 19 1/4" on 20" Disks smooth 19 1/2 To 19 3/4" on 20" Disks			
10- Harrow Bar Tines										
Diameter Length/ % Remaining										
11- Land Roller/ Tube Diameter										
Tube Thickness(Measure the End of Tube) (Measure the thickness on Tube Wall)										
Overall Summary of Unit							Nice looking unit, did not see any concerns with it, no leaks, no frame cracking, no wear issues. Looks like minimal use, will need a cleaning and annual service			