

Stock Number: 371762

Model: 4960

Serial Number: RW4960P006752



INSPECCIÓN EVALUACIÓN — ADVANCED — 6000 SERIES ROW-CROP TRACTORS AND EQUIVALENT MODELS EQUIPMENT ENTRY FORM

1993 John Deere 4960
Inventario: 371762
Serie: RW4960P006752
Garantía desconocida

LOCALIDAD ALMACENAMIENTO
C & B Operations, LLC - Slayton / 083635
Slayton, MN, 56172
Contacto:

FOTOS (0 Total)

RESUMEN

Estado general:
Comentarios
generales:
Horas:

	EXCELENTE	BIEN	MEDIANO	RAZONABLE	MAL	N/A	Observaciones	Costo estimado		
								Repuestos	Mano de obra	Total
Book-In Notes				X				0	0	0
Internal Notes						X		0	0	0

BOOK-IN NOTES

	N U E V O	B I E N	U T I L I Z A B L E	R E P A R A R	R E E M P L A Z A R	N D	Observaciones	Costo estimado		
								Repuestos	Mano de obra	Total
Engine Horsepower							220			
Cab										
Cab Options (Select all that apply)										
Radio (Select all that apply)										
Seat Options (Select all that apply)							plan to replace seat cushions			
Lights (Select all that apply)							✓ Standard Light Package Please see added lights on fenders			
Instructional Seat										
Transmission							✓ Powershift 15 spd			
Transmission Options (Select all That apply)										
Number of Forward Gears (Type In)										
Number of Reverse Gears (Type In)										
Hydraulic System							✓ Closed Center Hydraulic System			
Hydraulic Pump Gallons Per Minute (Type In number followed by GPM)										
Rear Remotes (Select all that apply)							✓ Three Rear Remotes			
PTO (Select all that apply)										
Three Point Hitch (Select all that apply)							✓ Category 3/3N Top link also included off due to type of use currently			
Rear Tire Size (Type In)							18.4-42 Firestone 23 deg			
Rear Tire Set up							Rear Duals on 30" spacing			
Rear Axle (Select all that apply)							✓ 118.5 Inches			
Rear Weights, Type in Actual Pounds or if Filled with Calcium Chloride or Rim Gaurd							inner 450x2 per side rear 1800lbs total			
Front Tire Size (Type In)							18.4-26			
Front Weights							✓ Twenty Front Weights			
Front Axle (Select all that apply)							✓ Mechanical Front Wheel Drive			
Fenders							✓ Pivoting Front Fenders			
Loader Options on Tractor (Select all that apply)							✓ Tractor is not Loader Ready			
Loader Model and Serial Number (Type In if equipped)										
Loader Leveling (If Equipped)										
Loader Hydraulics (Select all that apply if equipped)										
Loader Bucket Width (Type in width if equipped)										
Grapple (If Loader Equipped)										
Loader Options (Select all that apply)										
Precision Ag							✓ No Precision Ag Components			
Receiver							✓ No Receiver			
Display							no display			
Engine Heater							✓ Engine Block Heater			
Warranty							✓ No Warranty Remaining			
Operators Manual							✓ Operators Manual NOT Included			

INTERNAL NOTES

	N U E V O	B I E N	U T I L I Z A B L E	R E P A R A R	R E M P L A Z A R	N D	Observaciones	Costo estimado		
								Repuestos	Mano de obra	Total
Available Month & Year							its available now			
Inspect front axle pivot pins? Please take pictures of both							✓ Pins and bushings are good			
Inspect the entire MFD axle including all hub seals, axle seals and king pins?							✓ All MFWD components are good, no leaks			
Condition of all exterior tin and paint?			X				✓ Everything looks good this is a 30 year old tractor, its straight for its age			
Inspect complete tractor for leaks including under hood and under tractor.							✓ No Leaks			
Operate tractor checking transmission, MFD, diff lock, three-point, seat, air-conditioning, and the tilt column.							✓ Yes, every operates normally			
Loader Equipped, inspect all pins and bushings, frames for cracks and hydraulics for leaks							✓ No, add notes on what was found			
Overall condition of tractor? Please explain your selection.			X				tractor is not new paint-wise, recon figured for new cab kit to the interior and seat cushions to make the cab feel new again			
Overall condition of loader (If Equipped) Please explain your selection.						X				
Condition of tires										
Has the cab been smoked in?										
Are there currently any active codes in the display?							✓ NO			
All safety equipment in place and operational							✓ YES			
Are all emission components still in place and operational?							✓ YES			
Are there any visual signs or smell suggesting that mice have been in the cab?										
Pictures							✓ I took the pictures customer has owned this machine for 15 years, it will be a well maintained unit			
What reconditioning must be completed to resell this trade? Do not leave blank.										
Suggested ECV \$\$							\$5359			
Suggested Recon \$\$							43100 keeping retail less than \$45000			
Minimum of twenty pictures including hours and serial number							✓ YES enjoy the photos! Please let me know what you think of ECV I am running into a rock and a hard place on some of these trade deals as they were bid with Pat, then we are now getting these deals done thank you			
I am seeking an appraisal for:										
Customer purchasing same category unit?										
Is there more than one trade on the machine we are selling?										