



INSPECCIÓN EVALUACIÓN — ADVANCED — TRACTORS- 4WD, RX, RT, T JANUARY 2023

2022 John Deere 9RX 640

Inventario: 251013

Serie: 1RW9640DTNJ820597

Garantía desconocida

LOCALIDAD ALMACENAMIENTO

Pattison Agriculture Limited / 731849

Moosomin, SK, S0G3N0

Contacto:

FOTOS (0 Total)

RESUMEN

Estado general:
Comentarios
generales:
Horas:

							Costo estimado		
	E X C E L E N T E	B I E N	M E D I A N O	R A Z O N A B L E	M A L	N / A	Observaciones	Repuestos	Mano de obra Total
								0	00
MAIN FEATURES TO BE ADVERTISED - FILL IN FEATURES SECTION OF MFPRO								0	00
ADDITIONAL FEATURES FOR INFORMATION NOT TO BE ADVERTISED								0	00
Inspection/ Condition								0	00

Stock Number: 251013

Model: 9RX 640 Serial Number: 1RW9640DTNJ820597

								Costo estimado		
	N U E V O	B I E N	U T I L I Z A B L E	R E P A R A R	R E E M P L A Z A R	N D	Observaciones	Repuestos	Mano de obra	Total
Customer:							HGV			
Year: Make: Model:							2022 John Deere 9RX 640			
Serial Number:							1RW9640DTNJ820597			
Engine Hours:							1361			
Link to Picture Process:										

MAIN FEATURES TO BE ADVERTISED - FILL IN FEATURES SECTION OF MFPRO

								Costo estimado		
	N U E V O	B I E N	U T I L I Z A B L E	R E P A R A R	R E E M P L A Z A R	N D	Observaciones	Repuestos	Mano de obra	Total
1- Engine: Make / Size / H.P.							Cummins 14.9L 640hp.			
2- Transmission/ PowerTrain							✓ 18SP PS			
3- Front Tire: Brand and Size							✓ Tracks Camso Ag 3500 36"			
Weights/ Ballast Front							1548 kg. Suit Case Weights			
Rear Tires: Brand and Size							✓ Tracks Camso AG 3500 36"			
Weights/ Ballast Rear							430kg Suit Case Weights			
4- PTO							Yes			
5- HYD Pump Size							✓ 110GPM			
6- SCV's							✓ 8			
How many 3/4" Coupler's							3 Sets Of 3/4" Couplers			
7- Operator Station							✓ Premium Cab			
Operators Station Package (On MY22 and Newer)										
8- Misc.							✓ Hyd. Trailer Brakes			
9- AMS-Salesman Verifies if Going w/Unit Enter Into Attachments Section in Machine Features										
Display # 1 Make & Model							✓ John Deere Gen 4			
Serial #							PCG410B212233			
Display # 2 Make & Model							✓ John Deere Gen 4 Extended			
Serial #							PCG410A019589			
Activations							✓ CommandCenter Automation 4.0			
Receiver Make & Model							✓ John Deere Star Fire 6000			
Serial #							PCS161B238307			
Accuracy							✓ SF1			
10- Warranty Term & Deductible							✓ Original Factory BASIC WARRANTY 24m/2000h 16 Aug 2024 LIMITED BASIC 0m/0h 16 Aug 2025 EMISSIONS WARRANTY 60m/3000h 17 Aug 2027 EXTENDED WARRANTY (POWERTRAIN) 60m/4000h 16 Aug 2027 CAD-750.0			

Stock Number: 251013

Model: 9RX 640 Serial Number: 1RW9640DTNJ820597

ADDITIONAL FEATURES FOR INFORMATION NOT TO BE ADVERTISED

								Costo estimado		
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra	Total
Processor Serial Number							PCGUPSB888401			
MTG Serial Number							PCMA4GF596931			
Ethernet Cable							✓ Yes			
							✓ Greaseable Steering Pins			
# PSI Return Lines										

INSPECTION/ CONDITION

								Costo estimado		
	NUEVO	BIEN	UTILIZABLE	REPARAR	REEMPLAZAR	ND	Observaciones	Repuestos	Mano de obra	Total
1- Uses DEF X Si O No										
2- Pre Start Fluid Check							✓ Engine Oil			
Leaks							✓ Good			
3- Engine							✓ Stock			
4- Cooling Fan/ Oil Pan Gasket/ Front Timing Cover Leaks							✓ Good			
5- Operators Station							✓ Operators Manual No			
Cab/ Seat/ Glass Condition							✓ Good			
A/C/ Heat/ Radio							✓ Radio Working Yes			
6- Front Tires/ Tracks - Condition and % Remaining							A few marks in the lugs 96%			
Measured vs New Tread Height							62/32 64/32			
Rear Tires/ Tracks - Condition and % Remaining							A few marks and cuts in the lugs 93% See pictures			
Measured vs New Tread Height							62/32 64/32			
7-Front Final Drives/ Axle Seals							✓ Good			
8- Front Axle Pivot/ Hydra Cush							✓ Good			
9- Hinge Pins/ Steering Cyl.							✓ Good			
10- Rear Axel Seals/ SCV's/ PTO Pressure Return							✓ Good			
11- 3pt/ Drawbar							✓ Good			
12- Battery/ Exhaust/ Muffler							✓ Good			
13- 12.5/13.5L Water Pump Changed Turbo										
Exterior of Unit										
14- Body Panels/ All Safety Shields/ Hand Rails/ Steps/ Mirrors							✓ Good			
15- Function Test **IF POSSIBLE AND WITH PERMISSION ONLY**										
Overall Summary of Unit							Tractor has been well maintained will need a complete service and wash. The tracks have several cuts and chucks out of them			