

Stock Number: 247593

Model: 4720 Serial Number: 1LV4720HEDH916332



INSPECCIÓN EVALUACIÓN — ADVANCED — COMPACT UTILITY TRACTOR (CUT) JANUARY 2022

2013 John Deere 4720
Inventario: 247593
Serie: 1LV4720HEDH916332
Garantía desconocida

LOCALIDAD ALMACENAMIENTO
Pattison Agriculture Limited / 731793
North Battleford, SK, S9A 2Y7
Contacto:

FOTOS (0 Total)

RESUMEN

Estado general:
Comentarios
generales:
Horas:

								Costo estimado		
	E X C E L E N T E	B I E N	M E D I A N O	R A Z O N A B L E	M A L	N / A	Observaciones	Repuestos	Mano de obra	Total
MAIN FEATURES TO BE ADVERTISED - FILL IN FEATURES SECTION OF MFPRO								0	0	0
ADDITIONAL FEATURES FOR INFORMATION NOT TO BE ADVERTISED								0	0	0
INSPECTION/ CONDITION								0	0	0

Stock Number: 247593

Model: 4720 Serial Number: 1LV4720HEDH916332

							Costo estimado		
	N U E V O	B I E N	U T I L I Z A B L E	R E P A R A R	R E E M P L A Z A R	N D	Observaciones	Repuestos	Mano de obra Total
Customer:							Marlin Farms		
Tractor: Year: Make: Model:							2013 John Deere 4720		
Serial Number:							1LV4720HEDH916332		
Engine Hours:							1517		
Loader: Year: Make: Model:							2013 John Deere 400CX		
Serial Number:							1P0400CXPDX017901		
Link to Picture Process:									

MAIN FEATURES TO BE ADVERTISED - FILL IN FEATURES SECTION OF MFPRO

							Costo estimado		
	N U E V O	B I E N	U T I L I Z A B L E	R E P A R A R	R E E M P L A Z A R	N D	Observaciones	Repuestos	Mano de obra Total
1- Engine: Make / Size / H.P.							John Deere 2.4L 66hp		
2- Transmission							✓ MFWD Hydro		
3- PTO							✓ 540		
4- Tires							✓ Industrial		
Front Tire: Brand and Size							Titan 10-16.5 NHS		
Rear Tire: Brand and Size							Titan 16.9-24		
5- Operators Station							✓ Open Station Platform		
6- Hyd. Pump Size							5.1 GPM		
7- SCV's							✓ 3		
8- 3pt Hitch ☒ Si ☐ No									
9- Warranty									
10- Loader							✓ Self Leveling		
Loader Bucket Size							6'		
Loader Suspension ☐ Si ☒ No									
Bucket Level Indicator ☒ Si ☐ No									

ADDITIONAL FEATURES FOR INFORMATION NOT TO BE ADVERTISED

							Costo estimado		
	N U E V O	B I E N	U T I L I Z A B L E	R E P A R A R	R E E M P L A Z A R	N D	Observaciones	Repuestos	Mano de obra Total
							✓ HD Bucket		

Stock Number: 247593

Model: 4720 Serial Number: 1LV4720HEDH916332

INSPECTION/ CONDITION

								Costo estimado		
	N U E V O	B I E N	U T I L I Z A B L E	R E P A R A R	R E M P L A Z A R	N D	Observaciones	Repuestos	Mano de obra	Total
1- Pre Start Fluid Check							✓ Engine Oil			
Leaks							Bottom left and right of engine are dirty but could not find a wet spot where anything was leaking			
2- Operators Station										
Cab/ Seat/ Glass Condition										
Radio										
4- Front Tires/ Tracks - Condition and % Remaining							Good 88%			
Measured vs New Tread Height							15/32 17/32			
Rear Tires/ Tracks - Condition and % Remaining							Good 93%			
Measured vs New Tread Height							31/32 33/32			
Left Side of Unit										
5- Engine							✓ Stock			
6- Cooling Fan/ Oil Pan Gasket/ Engine Oil/ Coolant Leaks							✓ Good			
7- Front Axle Seals/ Pivot							✓ Good			
8- Tie Rods/ King Pins/ Trunnions (2WD)							✓ Good			
9- Front MFWD Drive Shaft/ U-Joints							✓ Good			
Rear Side of Unit:										
10- Rear Axel Seals/ SCV's/ PTO Pressure Return							✓ Good			
11- 3pt Hitch/ Drawbar							✓ Good			
Right Side of Unit										
12- Battery/ Exhaust/ Muffler							✓ Good			
Exterior of Unit										
13- Body Panels/ All Safety Shields/ Mirrors							✓ Good			
14- Loader Frame							✓ Good			
Loader Pins/ Bushings							✓ Good			
Loader Hyd. Cylinders/ Hoses							✓ Good			
Bucket/ Grapple/ Sileage Guard							✓ Good			
15- Function Test **IF POSSIBLE AND WITH PERMISSION ONLY**							Unit Ran Good			
Overall Summary of Unit							Overall this unit is in good shape, the seat is starting to crack. There are dirty spots on engine and hyd. valve but nothing is wet showing location of a leak. Unit needs to be washed and checked for any leaks. Unit needs a full service. Fan belt has a few cracks but still good.			