Stock Number: 233541 Model: S69Serial Number: 1H0S690SAE0765488



## INSPECCIÓN EVALUACIÓN — ADVANCED — COMBINE JANUARY 2022

2014 John Deere S690 Inventario: 233541 Serie: 1H0S690SAE0765488 Garantía desconocida LOCALIDAD ALMACENAMIENTO
Pattison Agriculture Limited / 731792
Unity, SK, S0K 4L0
Contacto:

### FOTOS (0 Total)

#### **RESUMEN**

Estado general: Comentarios generales: Horas:

								Costo estimado					
	EXCELENTE	B I E N	MEDIANO	RAZONABLE	M A L	N A	Observaciones	Repuestos	Mano de obra	Total			
								0	0	0			
MAIN FEATURES TO BE ADVERTISED - FILL IN FEATURES SECTION OF MFPRO								0	0	0			
ADDITIONAL FEATURES FOR INFORMATION NOT TO BE ADVERTISED								0	0	0			
Inspection/ Condition								0	0	0			

								Cost	Costo estimado		
	NUEVO	B I E N	UT I L I Z A B L E	R E P A R A R	REEMPLAZAR	N D	Observaciones	Repuestos	Mano de obra	Total	
Customer:							SPRINGWATER COLONY				
Year: Make: Model:							2014 John Deere S690				
Serial Number:							1H0S690SAE0765488				
Engine & Separator Hours:							3259 Eng. 2193 Sep.				
Link to Picture Process:											
Link to Auto Guide:											
Link to RTG											

#### MAIN FEATURES TO BE ADVERTISED - FILL IN FEATURES SECTION OF MFPRO

								Cost	o estimado		
	NUEVO	B I E N	UTILIZABLE	R E P A R A R	REEMPLAZAR	N D	Observaciones	Repuestos	Mano de obra	Tota	
1- Engine: Make / Size / H.P.							John Deere 13.5L 543HP Engine				
2- Drivetrain							✓ Prodrive/Harvestsmart				
3- Front Tire: Brand and Size							✓ Duals Michelin 520/85R42				
Rear Tires: Brand and Size							Michelin 750/65R26				
4- FeederHouse							✓ Fixed Speed				
5- Separation							✓ VariStream Rotor w/ Precision Feed Accelerator				
6- Concaves							✓ Howard				
7- Grain Tank							✓ Power Folding Hopper Covers				
8- Auger Length							✓ 26'				
9- Cleaning							/ Fixed Precleaner Single Zone Chaffer				
10- Chopper							✓ Fine Cut Chopper				
11- Operator Station							✓ Premium Cab Fridge				
Operators Station Package (On X9 Models Only)											
12- Cameras:										-	
13. Technology Options											
14- AMS-Salesman Verifies if Going w/Unit Enter Into Attachments Section in Machine Features											
Display # 1 Make & Model							✓ John Deere 2630				
Serial #							PCGU2UD487181 MTG - PCMAMGC613058				
Display # 2 Make & Model											
Serial #											
Activations							✓ Auto Trac				
Receiver Make & Model											
Serial #											
Accuracy							✓ SF1			•	
15- Warranty Term & Deductible											

## ADDITIONAL FEATURES FOR INFORMATION NOT TO BE ADVERTISED

							Cost	o estima	do
N U E V O	B I E N	UTILIZABLE	R E P A R A R	REEMPLAZAR	N D	Observaciones	Repuestos	Mano de obra	Total
						✓ Powder Fire Extinguisher			

# Stock Number: 233541

**INSPECTION/ CONDITION** 

			U		R		I	Cost	estima	do
	N U E V O	B I E N	UTILIZABLE	R E P A R A R	REEMPLAZAR	N D	Observaciones	Repuestos	Mano de obra	Total
1- Uses DEF										
X <sub>Si</sub> O <sub>No</sub>										
							✓ Engine Oil			
2- Pre Start Fluid Check							COOLANT AND ENGINE GEAR CASE LOW			
Leaks							✓ Good			
3- Operators Station							✓ Operators Manual Yes  NEEDS GOOD CLEASNING. RH GLOVE COMPARTMENT			
Cab/ Seat/ Glass Condition							HINGES BROKEN			
A/C/ Heat/ Radio							FAN WORKS COULD NOT RUN ENGINE.			
4- Front Tires/ Tracks - Condition and % Remaining							CRACKED MEGAXBIB 162B - 82%			
Measured vs New Tread Height							56/71			
Rear Tires/ Tracks - Condition							CRACKED MEGAXBIB 166B - 88%			
and % Remaining Measured vs New Tread Height							51/58			
5- Single Point/Front Drum							✓ Good	+ -	+	
6- Conveyor Chain Slats/ Top										
Sprockets							✓ Good			
7- FH Floor/Top Inspect Door/Stone Trap							✓ Good			
8- LH Final Drives							✓ N/R			
9- Primary Countershaft Gear							MINOR LEAKS			
Case/ Steady Bearing							✓ Good			
Unloading Auger Drive Chain							✓ Good			
10- Top Rotor Covers, Side Rail, Z Bar, Concave Hardware, Concave Shear System							TOP RAIL SMALL BEND. DIVIDER FINS ON STRATIFY PAN BENT. SMALL CRACK TOP OF SIDE FRAME OF CLEANING SHOE.			
Concaves, Thrashing Elements, Tine Grates, Tines							✓ Good			
11- Shoe Auger/ Keys/ Troughs							✓ N/R BACKLASH ON AUGERS NEED ADJUSTED			
12- Precleaner							✓ Good			
13- Walker Brgs										
14- LH Pitman Arms							✓ N/R PITMAN ARMS RUBBERS CRACKED. ALL SHOE ARMS ARE ORIGINAL.			
15- Hyd/ Pump/ Engine Gear							V N/R			
Case Leaks 16- Raise Chopper							LEAK ON HYD PUMP  Good			
17- Top Chaffer							✓ N/R			
<u> </u>							BROKEN IN LOTS OF PLACES			
18-Rear Beater/Overshot Discharge Beater/ Rear Walker Brgs							✓ Good			
Hammers Condition/ Stationary Knives							✓ Good BEEN FLIPPED ONCE ALREADY, CHOPPER DRIVE BELTS N/R			
19- Engine							Stock			
Engine Compartment							COULD NOT OPEN HOPPER COVERS, FRONT ENGINE MOUNT CRACKED			-
20- Grain Tank							✓ N/R			
Fountain Auger Flighting										
21- Re-Threshing Drive Chain/ RH Pitman Arms/ Return/ Clean Grain Elevator Chain/ Cross Auger							✓ Good ONLY TWO HAVE BEEN CHANGED. THEY REST ARE ORIGINAL			
22- RH Concaves/ Augers/ Hanger Tube,/ Separator							✓ Good			
23- RH Final Drive							✓ N/R MINOR LEAKS			
24- Rotor Top Cover/ Primary Counter Shaft/ Brgs							✓ Good			

Stock Number: 233541 Model: S696erial Number: 1H0S690SAE0765488

25- Feed Accelerator/ Belt/	✓ N/R	
Conveyor Chain Drive Chain/	FA DRIVE PULLEY BURNT. BELT N/R MINOR STONE DAMAGE	ĺ
Claas APS	TO FA	ĺ
26- Exterior	✓ N/R ***UNLOAD AUGER SCRAPED & DENTED LAST 6 FT N/R***	
27- Body Panels/ All Safety	✓ N/R	
Shields/ Hand Rails/ Steps	MISSING ALL SIDE SAFTTY SHIELDS	ĺ
28- Function Test **IF POSSIBLE AND WITH PERMISSION ONLY**	COULD NOT RUN	
Overall Summary of Unit	SEE ISSUES ABOVE. NO RECEIVER ON UNITAVERAGE CONDITION.	